


Ref no.:
CH/N/26/02/023

28/02/2026

To: All Members
致各會員：

Service Suspension



Temporary Suspension of Lift - Replacement of hoisting ropes, governor rope 暫停升降機服務 - 更換提升鋼纜及調速器鋼纜

Wednesday 星期三	Thursday 星期四	Friday 星期五
March 三月 4	March 三月 5	March 三月 6
早上 10:00 am – 下午 6:00 pm	早上 10:00 am – 下午 6:00 pm	早上 10:00 am – 下午 6:00 pm
Lift No. 1 1 號載客升降機		Lift No. 2 2 號載客升降機

**AFFECTED AREA: Lift No.1 and No.2 at
Club Bel-Air Peak Wing**
受影響範圍：朗峰會所 1 號及 2 號載客升降機

DETAILS 詳情:

Lift no.1 and 2 will be Temporarily suspended during the above working period.
We Apologize for any inconvenience caused.

1 及 2 號升降機服務將於上述時間暫停運作以進行上述工程。不便之處，敬請原諒。



Post Until
張貼至 06/03/2026

This notice has uploaded to Bel-Air website www.bel-air-hk.com and One-stop Mobile Apps
此通告已上載於貝沙灣網頁 www.bel-air-hk.com 及一站式手機應用程式

Island South Property Management Limited 南盈物業管理有限公司
(PMC Licence Number 物業管理公司牌照號碼：C-191466)
Club Bel-Air Bay Wing 貝沙灣灣畔會所：☎ 2989 9000 ✉ general-club@pccd.com
Club Bel-Air Peak Wing 貝沙灣朗峰會所：☎ 2989 6500 ✉ clubelair@pccd.com

